



Utility Conflict Report

| | | | | | | |
|-----------------------|-------------------------------------|--|-----------------|-----------------------|--------------------|--|
| OWNER | Utility | SAWS | Corridor | RIGSBY | SITE PHOTOS | |
| | Contact | ANN PECHE | ID | 307 | | |
| GENERAL INFO | Utility | WATER | | | |  |
| | Size and Material | STANDARD WATER VALVE, CAST IRON | | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | |
| | Longitudinal or Crossing | CROSSING | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | |
| LOCATION | Sheet No. | 97 | | | |  |
| | Station | 139+96.63 | | | | |
| | Offset | 3.51 | | | | |
| | Latitude | +29.397965 | | | | |
| | Longitude | -98.43076 | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | |
| | Test Hole No | N/A | | | | |
| | Test Hole Depth | N/A | | | | |
| RESOLUTION | Recommended Action | MINIMIZE - PROTECT IN PLACE | | | | |
| | Estimated Resolution Date | | | | | |
| | Resolution Status | UTILITY OWNER INFORMED OF UTILITY | | | | |
| | Comment | Valve within sidewalk accessible route | | | | |
| Date Collected | | Date Modified | | 11/28/2018 6:59:12 AM | | |