

Utility Conflict Report

OWNER	Utility	TxDOT	Corridor	NOGALITOS	SITE PHOTOS
	Contact	SUMAN SHRESTHA	ID	4012	
GENERAL INFO	Utility	STORM SEWER			
	Size and Material	STANDARD MANHOLE, CAST IRON			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	107+41.17			
	Offset	-26.126			
	Latitude	+29.387741			
	Longitude	-98.52279			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Unable to open manhole Back of curb to manhole = 2'-8"			
Date Collected		7/2/2018 10:39:06 AM		Date Modified 8/14/2018 4:38:26 PM	

