

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	SAWS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>		
	<b>Contact</b>	ANN PECHE	<b>ID</b>	4160			
<b>GENERAL INFO</b>	<b>Utility</b>	WATER					
	<b>Size and Material</b>	STANDARD WATER METER, CAST IRON					
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE					
	<b>Longitudinal or Crossing</b>	CROSSING					
	<b>Placement Relative to ROW</b>	INSIDE ROW					
<b>LOCATION</b>	<b>Sheet No.</b>	157					
	<b>Station</b>	683+85.98					
	<b>Offset</b>	21.95					
	<b>Latitude</b>	+29.356542					
	<b>Longitude</b>	-98.51217					
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE					
	<b>Test Hole No</b>	N/A					
	<b>Test Hole Depth</b>	N/A					
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT					
	<b>Estimated Resolution Date</b>						
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED					
	<b>Comment</b>	Front of sidewalk to meter = 3'-6" Meter to back of sidewalk = 6" Sidewalk width = 5'-0" Meter box filled with dirt, meter not visible Top of dirt to surface = 10" Lid flange thickness = 3/8" Total lid thickness = 1 7/8"					
<b>Date Collected</b>		8/2/2018 9:29:35 AM		<b>Date Modified</b>		12/18/2018 4:24:02 PM	

