

Utility Conflict Report

OWNER	Utility	CPS	Corridor	BANDERA	SITE PHOTOS
	Contact	BILL FEY	ID	4614	
GENERAL INFO	Utility	GAS			
	Size and Material	STANDARD GAS VALVE, CAST IRON			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	249			
	Station	1483+46.48			
	Offset	51.66			
	Latitude	+29.519270			
	Longitude	-98.636907			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment				
Date Collected		12/18/2018 2:29:38 PM	Date Modified		12/19/2018 11:48:22 AM

