

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	7139	
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC			
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER			
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	178			
	<b>Station</b>	766+54.91			
	<b>Offset</b>	-18.16			
	<b>Latitude</b>	+29.358335			
	<b>Longitude</b>	-98.55830			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED			
	<b>Comment</b>	Back of curb to pole = 4'-5" Pole diameter = 12" No pole ID Fence to pole = 3'-11" Underground cables 4 guy wires Pole to guy wire 1 (behind pole) = 1'-10" Pole to guy wire 2 (west of pole) = 13'-2" Fence to guy wire 1 (behind pole) = 5'-0"			
<b>Date Collected</b>		8/6/2018 11:38:31 AM	<b>Date Modified</b>		12/18/2018 4:02:30 PM

