

## Utility Conflict Report

|                     |                                     |   |                      |                      |                    |
|---------------------|-------------------------------------|---|----------------------|----------------------|--------------------|
| <b>OWNER</b>        | <b>Utility</b>                      | CPS   | <b>Corridor</b>      | NOGALITOS            | <b>SITE PHOTOS</b> |
|                     | <b>Contact</b>                      | JAKE MARTINEZ   | <b>ID</b>            | 3051                 |                    |
| <b>GENERAL INFO</b> | <b>Utility</b>                      | ELECTRIC  |                      |                      |                    |
|                     | <b>Size and Material</b>            | STANDARD POWER POLE, TIMBER   |                      |                      |                    |
|                     | <b>Accessible Route</b>             | ASSET IS OUTSIDE ACCESSIBLE ROUTE   |                      |                      |                    |
|                     | <b>Longitudinal or Crossing</b>     | CROSSING  |                      |                      |                    |
|                     | <b>Placement Relative to ROW</b>    | INSIDE ROW  |                      |                      |                    |
| <b>LOCATION</b>     | <b>Sheet No.</b>                    |   |                      |                      |                    |
|                     | <b>Station</b>                      | 138+42.34   |                      |                      |                    |
|                     | <b>Offset</b>                       | -28.5441  |                      |                      |                    |
|                     | <b>Latitude</b>                     | +29.394541  |                      |                      |                    |
|                     | <b>Longitude</b>                    | -98.51698   |                      |                      |                    |
| <b>SUE</b>          | <b>Level of Investigation Req'd</b> | NONE  |                      |                      |                    |
|                     | <b>Test Hole No</b>                 | N/A   |                      |                      |                    |
|                     | <b>Test Hole Depth</b>              | N/A   |                      |                      |                    |
| <b>RESOLUTION</b>   | <b>Recommended Action</b>           | NO CONFLICT   |                      |                      |                    |
|                     | <b>Estimated Resolution Date</b>    | 8/13/2018   |                      |                      |                    |
|                     | <b>Resolution Status</b>            | NO RESOLUTION WAS REQUIRED  |                      |                      |                    |
|                     | <b>Comment</b>                      | Pole ID: LW 43331; PL 414115<br>Pole marking: 1915<br>Pole to back of curb = 4'-11"<br>Pole to back of sidewalk = 11"<br>Sidewalk width = 4'-0"<br>Pole to fence = 1'-10" |                      |                      |                    |
|                     | <b>Date Collected</b>               |   | 7/11/2018 8:38:38 AM | <b>Date Modified</b> |                    |

