

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	AT&T	<b>Corridor</b>	SW LOOP 410	<b>SITE PHOTOS</b>		
	<b>Contact</b>	PHILIP AUSTIN	<b>ID</b>	7006			
<b>GENERAL INFO</b>	<b>Utility</b>	COMMUNICATIONS					
	<b>Size and Material</b>	STANDARD MANHOLE, CAST IRON					
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE					
	<b>Longitudinal or Crossing</b>	CROSSING					
	<b>Placement Relative to ROW</b>	INSIDE ROW					
<b>LOCATION</b>	<b>Sheet No.</b>						
	<b>Station</b>	283+42.56					
	<b>Offset</b>	-12.6506					
	<b>Latitude</b>	+29.374160					
	<b>Longitude</b>	-98.63864					
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE					
	<b>Test Hole No</b>	N/A					
	<b>Test Hole Depth</b>	N/A					
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT					
	<b>Estimated Resolution Date</b>	8/13/2018					
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED					
	<b>Comment</b>	Edge of pavement to manhole = 1'-6" Manhole to fence = 9'-7" Unable to open manhole					
<b>Date Collected</b>		8/2/2018 9:02:02 AM		<b>Date Modified</b>		8/14/2018 4:38:26 PM	

