

Utility Conflict Report

OWNER	Utility	CPS	Corridor	SW MILITARY	SITE PHOTOS		
	Contact	JAKE MARTINEZ	ID	4096			
GENERAL INFO	Utility	ELECTRIC					
	Size and Material	STANDARD POWER POLE, TIMBER					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station	535+89.93					
	Offset	15.57					
	Latitude	+29.358022					
	Longitude	-98.55844					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	11/21/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Pole ID: LW 55708; 422813 Back of curb to pole = 2'-4" Vertical difference between top of sidewalk and driveway = 3"-4"					
Date Collected		7/23/2018 10:31:38 AM		Date Modified		11/28/2018 6:59:12 AM	

