



Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS 
	Contact	ANN PECHE	ID	4183	
GENERAL INFO	Utility	SANITARY SEWER			
	Size and Material	STANDARD MANHOLE, CAST IRON			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	160			
	Station	698+36.94			
	Offset	18.9002			
	Latitude	+29.356576			
	Longitude	-98.50762			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Top of cone to surface = 1'-1 1/2" Lid thickness = 1 1/2" Manhole to back of curb = 4'-9" Sidewalk width = 6'-6"			
Date Collected		8/6/2018 8:46:57 AM		Date Modified	12/17/2018 3:06:04 PM

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800