

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|--|-----------------|----------------------|--------------------|-----------------------|--|
| OWNER | Utility | CPS | Corridor | SW MILITARY | SITE PHOTOS | | |
| | Contact | JAKE MARTINEZ | ID | 4196 | | | |
| GENERAL INFO | Utility | ELECTRIC | | | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | 162 | | | | | |
| | Station | 715+96.33 | | | | | |
| | Offset | 16.12 | | | | | |
| | Latitude | +29.356665 | | | | | |
| | Longitude | -98.50205 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | | | |
| | Estimated Resolution Date | 11/21/2018 | | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | Pole to back of curb = 2'-11" Pole to back of sidewalk = 2'-9" Sidewalk width = 6'-10" No pole ID Pole attached to adjacent pole | | | | | |
| Date Collected | | 8/6/2018 11:01:29 AM | | Date Modified | | 11/28/2018 6:59:12 AM | |

