

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	BANDERA	SITE PHOTOS
	Contact	ANN PECHE	ID	4585	
GENERAL INFO	Utility	WATER			
	Size and Material	UNKNOWN			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	340			
	Station	2516+80			
	Offset	20			
	Latitude	+29.483072			
	Longitude	-98.59773			
SUE	Level of Investigation Req'd	QLA			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	GIS indicates that a waterline could be located beneath proposed bus pad. Request As-builts for line depth verification			
Date Collected		Date Modified		12/19/2018 11:48:29 AM	

