

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS		
	Contact	JAKE MARTINEZ	ID	3028			
GENERAL INFO	Utility	ELECTRIC					
	Size and Material	STANDARD POWER POLE, TIMBER					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station	125+69.29					
	Offset	-53.7614					
	Latitude	+29.391950					
	Longitude	-98.51951					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	8/13/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Pole marking: 205 Pole to back of curb = 2'-8 1/2" Pole to face of wall at flare = 4'-0" Sidewalk width (at pole) = 7'-8" Sidewalk width (typical) = 4'-0" Guy wire vertical clearance = 9'-10" Pole to guy wires = 8'-4"; 10'-1"; 17'-7"					
Date Collected		7/10/2018 10:16:37 AM		Date Modified		8/14/2018 4:38:26 PM	

