

Utility Conflict Report

OWNER	Utility	TxDOT	Corridor	NOGALITOS	SITE PHOTOS		
	Contact	SUMAN SHRESTHA	ID	3046			
GENERAL INFO	Utility	UNKNOWN					
	Size and Material	UNKNOWN					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station	135+10.45					
	Offset	-26.2256					
	Latitude	+29.393787					
	Longitude	-98.51746					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	8/13/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Emergency vehicle crossing traffic signal Back of curb to pole base = 2'-6" Pole base to face of curb = 2'-8" Sidewalk width = 6'-3"					
Date Collected		7/11/2018 8:05:20 AM		Date Modified		8/14/2018 4:38:26 PM	

