

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS
	Contact	JAKE MARTINEZ	ID	3065	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	86			
	Station	136+44.22			
	Offset	22.499			
	Latitude	+29.394089			
	Longitude	-98.51720			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date				
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Pole to back of sidewalk = 6'-0" Pole to water valve (no lid) = 1'-10" No pole ID FO CATV cable			
	Date Collected	7/11/2018 11:35:49 AM	Date Modified	8/15/2018 12:40:04 PM	

