

## Utility Conflict Report

|                       |                                     |   |                 |                      |                    |                       |  |
|-----------------------|-------------------------------------|---|-----------------|----------------------|--------------------|-----------------------|--|
| <b>OWNER</b>          | <b>Utility</b>                      | SAWS  | <b>Corridor</b> | NOGALITOS            | <b>SITE PHOTOS</b> |                       |  |
|                       | <b>Contact</b>                      | ANN PECHE   | <b>ID</b>       | 3074                 |                    |                       |  |
| <b>GENERAL INFO</b>   | <b>Utility</b>                      | WATER   |                 |                      |                    |                       |  |
|                       | <b>Size and Material</b>            | STANDARD WATER METER, STEEL   |                 |                      |                    |                       |  |
|                       | <b>Accessible Route</b>             | ASSET IS OUTSIDE ACCESSIBLE ROUTE   |                 |                      |                    |                       |  |
|                       | <b>Longitudinal or Crossing</b>     | CROSSING  |                 |                      |                    |                       |  |
|                       | <b>Placement Relative to ROW</b>    | INSIDE ROW  |                 |                      |                    |                       |  |
| <b>LOCATION</b>       | <b>Sheet No.</b>                    | 88  |                 |                      |                    |                       |  |
|                       | <b>Station</b>                      | 140+52.28   |                 |                      |                    |                       |  |
|                       | <b>Offset</b>                       | 25.5217   |                 |                      |                    |                       |  |
|                       | <b>Latitude</b>                     | +29.395010  |                 |                      |                    |                       |  |
|                       | <b>Longitude</b>                    | -98.51639   |                 |                      |                    |                       |  |
| <b>SUE</b>            | <b>Level of Investigation Req'd</b> | NONE  |                 |                      |                    |                       |  |
|                       | <b>Test Hole No</b>                 | N/A   |                 |                      |                    |                       |  |
|                       | <b>Test Hole Depth</b>              | N/A   |                 |                      |                    |                       |  |
| <b>RESOLUTION</b>     | <b>Recommended Action</b>           | NO CONFLICT   |                 |                      |                    |                       |  |
|                       | <b>Estimated Resolution Date</b>    |   |                 |                      |                    |                       |  |
|                       | <b>Resolution Status</b>            | NO RESOLUTION WAS REQUIRED  |                 |                      |                    |                       |  |
|                       | <b>Comment</b>                      | Top of meter to surface = 6"<br>Rubber lid thickness = 2"<br>Face of wall to meter = 8"<br>Raise meter enclosure to top of wall (approx 4") |                 |                      |                    |                       |  |
| <b>Date Collected</b> |                                     | 7/11/2018 2:38:41 PM  |                 | <b>Date Modified</b> |                    | 8/15/2018 12:41:11 PM |  |

