

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	3082	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD FIRE HYDRANT			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	120			
	Station	506+56.40			
	Offset	29.4447			
	Latitude	+29.358965			
	Longitude	-98.56769			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/14/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Back of curb to hydrant = 3'-4"			
Date Collected		7/19/2018 8:09:19 AM		Date Modified 11/28/2018 6:59:12 AM	

