

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|--|-----------------|----------------------|--------------------|-----------------------|--|
| OWNER | Utility | CPS | Corridor | SW MILITARY | SITE PHOTOS | | |
| | Contact | JAKE MARTINEZ | ID | 3105 | | | |
| GENERAL INFO | Utility | ELECTRIC | | | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | 132 | | | | | |
| | Station | 541+91.18 | | | | | |
| | Offset | 15.9398 | | | | | |
| | Latitude | +29.357874 | | | | | |
| | Longitude | -98.55659 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | | | |
| | Estimated Resolution Date | | | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | Pole ID: 476612 Pole marking: - 294 Wire fence to pole = 4'-7" Back of curb to pole = 2'-11" Back of curb to mailbox = 1'-9" CATV Cable | | | | | |
| Date Collected | | 7/24/2018 8:14:33 AM | | Date Modified | | 11/28/2018 6:59:12 AM | |

