

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	3151	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD FIRE HYDRANT			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	143			
	Station	589+87.51			
	Offset	17.4827			
	Latitude	+29.356366			
	Longitude	-98.54132			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date				
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Hydrant to front of sidewalk = 2'-5" Sidewalk width = 4'-5"			
Date Collected		7/31/2018 11:09:43 AM		Date Modified 11/28/2018 6:59:12 AM	

