

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	
	Contact	JAKE MARTINEZ	ID	4046	
GENERAL INFO	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	74			
	Station	116+02.73			
	Offset	22.94			
	Latitude	+29.389602			
	Longitude	-98.52119			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Pole to back of curb = 2'-0" Sidewalk width = 4'-0" No pole ID found Adjacent to existing VIA bus stop			
Date Collected		7/3/2018 8:34:52 AM		Date Modified	9/13/2018 2:01:24 PM

SITE PHOTOS

