

Utility Conflict Report

| | | | | | |
|-----------------------|-------------------------------------|---|-----------------|--|--------------------|
| OWNER | Utility | SAWS | Corridor | SW MILITARY | SITE PHOTOS |
| | Contact | ANN PECHE | ID | 4130 | |
| GENERAL INFO | Utility | WATER | | | |
| | Size and Material | STANDARD FIRE HYDRANT | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | |
| | Longitudinal or Crossing | CROSSING | | | |
| | Placement Relative to ROW | INSIDE ROW | | | |
| LOCATION | Sheet No. | 148 | | | |
| | Station | 636+50.32 | | | |
| | Offset | 19.4664 | | | |
| | Latitude | +29.356464 | | | |
| | Longitude | -98.52704 | | | |
| SUE | Level of Investigation Req'd | NONE | | | |
| | Test Hole No | N/A | | | |
| | Test Hole Depth | N/A | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | |
| | Estimated Resolution Date | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | |
| | Comment | Hydrant to back of curb = 4'-3" Sidewalk width = 6'-8" | | | |
| Date Collected | | 8/1/2018 8:07:57 AM | | Date Modified 11/28/2018 6:59:12 AM | |

