

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS		
	Contact	ANN PECHE	ID	7126			
GENERAL INFO	Utility	WATER					
	Size and Material	STANDARD FIRE HYDRANT					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.	184					
	Station	783+50.02					
	Offset	-17.9734					
	Latitude	+29.357798					
	Longitude	-98.55273					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date						
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Hydrant to edge of driveway (measuring perpendicular to roadway) = 2'-9" Back of curb to hydrant = 4'-6" Pole to hydrant = 3'-11"					
Date Collected		8/6/2018 10:17:13 AM		Date Modified		11/28/2018 6:59:12 AM	

