

Utility Conflict Report

OWNER	Utility	CHARTER	Corridor	NOGALITOS	SITE PHOTOS
	Contact	FRANK CYPRIAN	ID	1023	
GENERAL INFO	Utility	COMMUNICATIONS			
	Size and Material	OVERHEAD TELECOMM LINES			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	89			
	Station	140+95.65			
	Offset	22.01			
	Latitude	+29.395026			
	Longitude	-98.51630			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Related to utility ID 3075			
Date Collected		Date Modified		9/13/2018 2:02:14 PM	

